

**ACKNOWLEDGEMENT FAX SHEET OF RECEIPT OF DEFECT  
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04V-169 by the  
National Highway Traffic Safety Administration

**Part 573 Report Date:** April 1, 2004

**Date E-Mailed:** April 13, 2004

**MANUFACTURER:** PACCAR, Inc.

**MANUFACTURER CONTACT:** Mr. Kenneth R. Brownstein, Senior Counsel  
Mr. Paul Giampapa

**FAX:** 425-468-8228


**SUBJECT:** 2,586 PACCAR 2003-2004 Kenworth T300 trucks equipped with Caterpillar C7 or 3126B 2002 engines and Horton fan hubs and manufactured from September 2, 2002 through February 9, 2004. The fan hub mounting bolts can fail resulting in the hub and fan assembly separating from the engine. (*Kenworth Recall No. 03KW9*)

This is an acknowledgment for this recall. A formal acknowledgment letter will be written if we have additional comments or concerns.

We have reviewed your proposed owner notification and it meets the requirements of Part 577.

As stated in your report, this recall will be extended to include six calendar quarters following the new notification to the customers. Please let this office know the date you begin mailing and as usual provide this office with any final documents of this recall.

If you have any questions, please call:

 Judith Taylor, Safety Defects Analyst on (202) 366-9525 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [judy.Taylor@nhtsa.dot.gov](mailto:judy.Taylor@nhtsa.dot.gov)  
Recall Management Division